Efectis Nederland BV



Efectis Nederland BV Centre for Fire Safety Lange Kleiweg 5 P.O. Box 1090 2280 CB Rijswijk

Efectis Nederland report

2009-Efectis-R0103(E)

Determination of the resistance to fire according to EN 1365-2:1999 of a floor construction consisting of wooden beams with a Lewis® floor on top. Anticipated fire resistance: 60 minutes

www.efectis.nl

T +31 15 276 34 80 F +31 15 276 30 25 E nederland@efectis.nl

Date March 2009

Author(s) P.W.M. Kortekaas

Ing. P.G.R. Scholten

Number of pages 9 (excluding appendices)

Number of appendices 3 (A to C)

Sponsor Reppel B.V.

p.o. box 102

3300 AC Dordrecht The Netherlands

Project name Resistance to fire of a wooden floor ceiling construction

Project number 2008770

All rights reserved.

No part of this publications may be reproduced and/or published by print, photoprint, microfilm or any others means without the previous written consent of Efectis.

In case this report was drafted on instructions, the rights and obligations of contracting parties are subject to either the Standard Conditions for Research Instructions given to TNO, or the relevant agreement concluded between the contracting parties. Submitting the report for inspection to parties who have a direct interest is permitted.

© 2009 Efectis Nederland BV: a TNO company

This report is issued by Efectis Nederland BV (previously **TNO** Centre for Fire Research). Efectis Nederland BV and her sister company Efectis France are full subsidiaries of Efectis Holding SAS since 1 January 2008, in which the Dutch TNO and the French CTICM participate. The activities of the TNO Centre for Fire Research were privatized in Efectis Nederland BV since 1st July 2006. This is in response to international developments and requests by customers. In order to be able to give a better answer to the customer's request and offer a more comprehensive service of high quality and a wider range of facilities, the international collaboration has been further expanded. This is done with highly experienced partners in fire safety in Norway (Sintef-NBL), Spain (Afiti-Licof), Germany (IFT), USA (South West Research Institute) and China (TFRI). Further information can be found on our website.

Contents

1	Subject3
2	Investigation3
3	Sponsor3
4	Place and data regarding the investigation3
5	Date and number of the test report3
6	Investigated construction4
6.1	General4
6.2	Method of assembly5
7	Manufacturing of the test specimen5
8	Course of investigation5
8.1	Verification of the specimen5
8.2	Conditioning5
8.3	Density and humidity measurements6
8.4	Fire test6
9	Observations
9.1	Observations during heating
9.2	Graphs of the results7
9.3	Uncertainty of measurement
10	Summary7
11	Field of direct application8
12	Figures9

Appendices

- A Furnace conditions
- B Positions of the thermocouples and measurement results
- C Photos

1 Subject

A wooden floor construction which was protected on the underside by 1 layer of gypsum board and on the top side by a Lewis® floor with a 50 mm thick layer of Beamix concrete.

2 Investigation

Determination of the resistance to fire according to EN 1365-2:1999.

3 Sponsor

Reppel B.V. P.o. Box 102 3300 AC DORDRECHT

4 Place and data regarding the investigation

The investigation took place at the laboratory of Efectis Nederland BV in Rijswijk, The Netherlands.

Mounting of the Lewis floor, the concrete cover and the gypsum boards by the sponsor Fire test:

Monday the 16th of June 2008 Monday the 14th of July 2008

5 Date and number of the test report

March 2009, 2009-Efectis-R0103(E).

6 Investigated construction

6.1 General

Investigated was a wooden floor construction.

For details we refer to figure 1 and the description mentioned below.

6.1.1 Wooden beams

Material : Pinewood
Cross section : 100 x 200 mm
Centre-to-centre distance : 500 mm
Span : 4150 mm

6.1.2 Ceiling channel on the underside of the floor

Type : BPB resilient ceiling channel

Centre-to-centre distance : 500 mm

Fixing : grabber screws 25 mm, 2 per beam

6.1.3 Gypsum boards

Type : BPB Gyproc RF 12.5 mm

- Thickness : 12.5 mm

Number of layers : 1

Fixing
 grabber screws 35 mm, c.t.c. distance 300 mm
 Joints
 covered with paper tape and covered with BPB

Promix Premium joint mortar

6.1.4 Lewis® floor

Type : Lewis platesOverlap between plates : min. 100 mm

Fixing : the Lewis plates are joint together by self tapping

screws Ø 4.2 x 16 mm. The floor is not connected to

the wooden beams

Support : between the Lewis plates and the top of the wooden

beams Rockwool of 25 mm thick and 100 mm wide

6.1.5 Concrete floor

- Type : Beamix

- Thickness : 50 mm (34 mm over the top of the Lewis plates)

6.2 Method of assembly

- Mounting of aerated concrete frame
- Mounting of the beams
- Mounting of the Rockwool strips on top of the beams
- Mounting of the Lewis plates
- Casting of the concrete floor
- Mounting of the ceiling channels
- Mounting of the gypsum boards

7 Manufacturing of the test specimen

Reppel BV	Lewis floor	
	Concrete floor	
	Gypsum boards	
Efectis Nederland BV	Test frame	
	Wooden beams	

8 Course of investigation

8.1 Verification of the specimen

During mounting the used materials and parts were verified against the supplied data. Efectis was not involved in the selection of the materials.

8.2 Conditioning

From the moment of installation until the fire test the construction was stored in the laboratory of Efectis Nederland BV with the following conditions:

- Ambient temperature: 20 ± 5 °C.
- Relative humidity: $50 \pm 10 \%$.

8.3 Density and humidity measurements

The density¹ and the moisture equilibrium² of the materials were determined.

Table 1: material properties

Tuote 1. material properties					
Material	Density	Moisture content			
	$[kg/m^3]$	[%]			
Wooden beams	392	7.0			
Gypsum boards	869	0.6			
Concrete floor	2128	1.8			

8.4 Fire test

8.4.1 Test conditions

The test was performed under the conditions as specified in EN 1365-2:1999.

The test specimen was heated on one side using the standard fire curve.

The pressure in the furnace that was aimed for was 20 Pa at 100 mm below the floor construction.

8.4.2 Load on the floor

A load of 2 kN/m² was applied on the floor

8.4.3 Measurements

During the heating the following data were measured and registered:

Furnace conditions:

- gas temperatures inside the furnace with plate thermometers, regularly spread over the directly heated surface.
- Pressure in the furnace at measured at 100 mm below the floor construction

Test specimen

- The surface temperatures of the floor construction;
- The deformations of the floor construction

Ambient

• ambient temperature in the laboratory.

The thermocouple positions are given in figure B1.

With a cotton wool pad and calipers the integrity criterion was checked.

² Determined after drying for 24 hours at 60°C for the gypsum board and 24 hours at 105°C for the wooden beam and the concrete floor

¹ Determined before drying

9 Observations

9.1 Observations during heating

See the table below for detailed observations during heating.

Time [min.]	Observations
0	Start of heating
20	Till the 20 th minute of heating the pressure measurement was on the
	wrong measuring channel. During this time the pressure was
	monitored at a secondary no registering pressure meter. The pressure
	was within the limits. After 20 minutes the problem was solved
35	One edge of a gypsum board comes loose
39	Gypsum board deforms and is resting on the plate thermocouples
40	A corner of a gypsum board comes loose
45	The beams near the support color black
49	2 beams can be viewed from below
52	1 gypsum board collapses
54	2 nd gypsum board in the middle collapses
56	More gypsum board are collapsing
77	Temperature rise at TK1=181°C
79	End of heating

The photos in annex C show the construction before, during and after heating.

9.2 Graphs of the results

The measurement results are presented in the form of graphs in annex B and C.

During heating the temperature and the air speed in the laboratory fulfilled the criteria of EN 1363-1:1999.

9.3 Uncertainty of measurement

Because of the nature of fire resistance testing and the consequent difficulty in quantifying the uncertainty of measurement of fire resistance, it is not possible to provide a stated degree of accuracy of the result.

10 Summary

The fire resistance to fire of a wooden floor construction which was protected on the underside by one layer gypsum board and on the topside by a Lewis® floor with a 50 mm thick cover of Beamix concrete has been determined according to EN 1365-2:1999.

Table 2: summary of results

Criterion	Time in minutes from the start of the test till the time a criterion according to EN 1365-2:1999 was reached		
	EN 1365-2:1999	Criterion	
a) Load bearing capacity	79	Not exceeded	
b) Integrity (E)			
 Cotton wool pad 	79	Not exceeded	
Gap gauges	79	Not exceeded	
 Sustained flaming 	79	Not exceeded	
c) Thermal insulation (I)			
 Average temperature rise 	79	Not exceeded	
 Maximum temperature rise 	77	exceeded	

The heating was terminated after 79 minutes at the request of the sponsor.

The classification according to EN 13501-2 shall be given in a separate document.

11 Field of direct application

This report details the method of construction, the test conditions and the results obtained when the specific element of construction described herein was tested following the procedure outlined in EN 1363-1, and where appropriate EN 1363-2. Any significant deviation with respect to size, constructional details, loads, stresses, edge or end conditions other than those allowed under the field of direct application in the relevant test method is not covered by this report.

The summary of chapter 10 is only valid for floor constructions with their hardware and materials that are in detail equal to the construction described in this report and that also fulfill the following requirements:

- a) With a height of the plenum of at least 200 mm;
- b) With a centre-to-centre distance of the beams of maximum 500 mm;
- c) With maximum bending moments and shear forced no larger than tested;
- d) With dimensions of the gypsum equal or smaller than tested.

P.W.M. Kortekaas

P.G.R. Scholten B.Sc

This report is issued by Efectis Nederland BV (previously **TNO** Centre for Fire Research). Efectis Nederland BV and her sister company Efectis France are full subsidiaries of Efectis Holding SAS since 1 January 2008, in which the Dutch TNO and the French CTICM participate. The activities of the TNO Centre for Fire Research were privatized in Efectis Nederland BV since 1st July 2006. This is in response to international developments and requests by customers. In order to be able to give a better answer to the customer's request and offer a more comprehensive service of high quality and a wider range of facilities, the international collaboration has been further expanded. This is done with highly experienced partners in fire safety in Norway (Sintef-NBL), Spain (Afiti-Licof), Germany (IFT), USA (South West Research Institute) and China (TFRI). Further information can be found on our website.

Figures 12




Figure 1: overview of the test specimen

A Furnace conditions

Figure A1 : measured gas temperatures in the furnace

Figure A2 : relative deviation of the furnace temperatures

Figure A3 : ambient temperature in the laboratory during the test

Figure A4 : measured pressure in the furnace




Figure A1 : measured gas temperatures in the furnace




Figure A2 : relative deviation of the furnace temperatures




Figure A3 : ambient temperature in the laboratory during the test




Figure A4 : measured pressure in the furnace

B Positions of the thermocouples and measurement results

Figure B1: positions of the thermocouples

Figure B2: measured air temperatures in the plenum

Figure B3: measured surface temperatures on top of the floor

Figure B4: measured deformation of the floor




Figure B1: Positions of the thermocouples




Figure B2: measured air temperatures in the plenum




Figure B3: measured surface temperatures on top of the floor




Figure B4: measured deformation of the floor

C Photos




Photo 1: view of the floor before casting the concrete



Photo 2 : detail of the mounting of the ceiling channels



Photo 3: detail of the mounting of the gypsum boards



Photo 4: view of the construction before the test